

1. In a computer system coupled to a plurality of UPS devices through a network, a method of monitoring a state of the UPS devices comprising:

generating a UPS devices monitoring icon on a computer display, wherein the UPS

10 devices monitoring icon has a first symbol that indicates all the UPS devices being managed by the computer system are in a normal state; and

causing the UPS devices monitoring icon to change to a second symbol when at least one UPS device being managed changes to an abnormal state.

0927822.03.001